Beeline v2.0.3

Release Notes

Introduction

These Release Notes detail the key changes to software components for Beeline v2.0.3 since the v2.0.2 release.

NEW FEATURES:

- None.

DEFECT REPAIRS:

- Removed the user authentication functionality. A recent update of the authentication platform is causing the authentication to fail preventing our user to complete the installation of the Beeline software successfully.
- Fixed an issue in the Beeline Charts. They now are consistent with the GenomeStudio Controls Dashboard charts.

KNOWN ISSUES:

- None